

issues

MANDATORY BULLETIN No. BB/19a

- 1. WITH REFERENCE TO:** Special shaped hot air balloon of BB FWEIN type, S/N 161
- 2. REASON:** DS modification – implementation of the parachute and rotation vent
- 3. REQUIRED ACTION:**
- 1) Change of the relevant sheets of the Flight Manual Supplement
 - 2) The bulletin No. BB/13a should be cancelled
- 4. DEADLINE FOR ACTION:** Immediately
- 5. ACTION CARRIED OUT:** Manufacturer
- 6. INDUCED COST COVERED:** None
- 7. NECESSARY MATERIAL:** None
- 8. PROCESS:**
- 1) Cancel the relevant sheets of the present Flight Manual Supplement
 - 2) Insert the new ones (Change 1, Issue 1.2.2002)
 - 3) Cancel the mandatory bulletin No. BB/13a
- 9. BULLETIN TAKES EFFECT:** From the date of the CAA, Czech Republic approval.
- 10. ENCLOSURES:** Sheets: 1/2, 3/4 5/6, 7/8, 9/10, 11/ILB

On behalf of the manufacturer:

Ing. Josef Pučégl

Date: 1.2.2002

